

REPORT.

The lode line of this claim was run directly upon the ground, and the several corners established by means of offsets from the lode line. All tie lines were run either directly upon the ground or by traverses, run upon the ground and submitted in a separate report herewith.

The S. E. Cor. Sec. 4, T. 26 S., R. 64 E., M.D.M., is a porphyry rock 7x9 ins., standing 14 ins. above the ground, with mound of rock, chiseled with five notches on the South face and three notches on the East face.

The W. $\frac{1}{4}$ Sec. Cor., Sec. 2, T. 26 S., R. 65 E., M.D.M., is a mesquite post, about 4 ins. in diameter, standing 3 ft. above a mound of stone, scribed $\frac{1}{4}$ on its east face. There are other marks upon it which have weathered until they are no longer decipherable. These are the nearest standing corners of the public survey that can be found and identified.

The Red Butte lode is supposed to be adjoined by the Keystone lode, unsurveyed, on the north, the Red Butte Extension lode, unsurveyed, on the east, and the Soldier Boy lode, unsurveyed, on the south, all of which were at one time held by the Little Eldorado Mining Company. But no corners to these or other adjoining lodes could be found and identified.

NOTE;-- The discrepancies between these field notes and the amended certificate of location of the Red Butte lode and the certificate of location of the Red Butte Mill Site are due to errors in said certificates. The Certificate of location of the Red Butte Mill Site is also in error in stating that said Mill Site is bounded on the south by the Techatticup Mill Site. The survey of said Red Butte Mill Site was made in strict conformity to the certificate of location thereof and a plat furnished by claimant, and is presumably identical with the location thereof, although Cors. Nos. 3 and 5 were not found in place, having been destroyed by the caving of the bank of the Colorado River, due to the gradual encroachment of the river at this point.