

Survey No. 4215

Description of Corners.

The N.W. cor. of Sec. 34, T. 46. N., R. 58. E. of the M. D. R. and M. S. find to be a granitic rock, $10 \times 6 \times 6$ ins. above ground, firmly set in the ground, marked with 3 grooves on N. and E. faces, and S.E. on N. face, with a mound of stones on W. side.

Sur. No. 4076. Shovel Fraction Code.

Cor. No. 1. is a balckam post, 4 ins. square, beared, firmly set in mound of earth and stone, and showing 1.5 ft. above same, soured S. Fr. 1-4076.

Cor. No. 2. is a mahogany post, 5×4 ins. square, beared, firmly set and showing 2.5 ft. above mound of stones, soured S. Fr. 2-4076.

Sur. No. 4076. Shovel Code.

Cor. No. 4. is a balckam post, 4 ins. square, beared, showing 3 ft. above rock mound, firmly set, soured S. 4-4076.

Bluater Code, unsurveyed.

The conflict with this claim is shown or returned by me in accordance with the additional and amended location certificate thereof dated Aug. 2, 1911. Based on the position of Cor. No. 6. thereof which is identical with Cor. No. 4. Sur. No. 4076, Shovel Code, as found by me on the ground,

Errors.

I find course of line 1-2. Sur. No. 4076, Shovel Fraction Code, to be N. $69^{\circ} 11'$ E. instead of N. $69^{\circ} 14'$ E. as per records.

Note: Neither my assistants nor myself held any interest in this claim at time of this survey.

Note: I find connections from Cor. No. 1. Sur. No. 4076, Shovel Fraction Code, to Cor. No. 2. Sur. No. 4005, Dutch Flat Code, and to S.W. cor. Sec. 34, T. 46.

N. R. 58. E. to be N. $69^{\circ} 04' 05''$ W. 2480.2 ft. \pm S. $82^{\circ} 22' 49''$ E. 6814.8 ft. \pm as per trip.