

## Mineral Survey No. 5017

FEET	<p>The collar of drill hole No. 88-254-RC is within the Sideline 1F lode of this survey.</p> <p>The collar of drill hole No. 88-252-RC is within the original location of the Sideline 31F lode.</p> <p>Five hundred dollars or over has been expended in such a manner as tends to the development of each lode included in a common improvement, subsequent to its location and to the time since which common ownership and contiguity have prevailed; therefore, an equal interest is credited to each claim with a common improvement.</p> <p style="text-align: center;"><b>OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA</b></p> <p>The true point for the cor. for Secs. 28, 29, 32 and 33, T. 39 N., R. 42 E., M.D.M., is not monumented and it bears N. 3°11'29" E., 256.74 ft. from the witness corner instead of N. 3°08' E. as approved.</p> <p>The 1/4 sec. cor. of Secs. 28 and 29, T. 39 N., R. 42 E., M.D.M., monumented with a 2-1/2 in. diam. iron pipe and brass cap properly mkd. The South 1/2 mile on the West bdy. of Sec. 28 bears N. 0°34'42" W., 2616.20 ft., instead of N. 0°37' W., 2617.23 ft. as approved.</p> <p>The 1/4 sec. cor. bet. Secs. 28 and 33, T. 39 N., R. 42 E., M.D.M., was not found. The cor. of Secs. 27, 28, 33 and 34, T. 39 N., R. 42 E., M.D.M., monumented with a 2-1/2 in. diam. iron pipe and brass cap properly mkd. The South bdy. of Sec. 28 bears S. 89°01'42" W., 5243.99 ft., instead of S. 89°01' W., 5243.04 ft. as approved.</p> <p>The East 1/2 mile on the South bdy. of Sec. 29 bears S. 89°17'56" W., 2623.99 ft., instead of S. 89°15' W., 2622.51 ft. as approved. The cor. of Secs. 29, 30, 31 and 32, T. 39 N., R. 42 E., M.D.M., monumented with a 2-1/2 in. diam. iron pipe and brass cap properly mkd. The West 1/2 mile on the South bdy. of Sec. 29 bears S. 89°18'31" W., 2621.63 ft., instead of S. 89°15' W., 2622.51 ft. as approved.</p>
------	--