

Mineral Survey No. 5017

FEET							
	<p>The North 1/2 mile on the East bdy. of Sec. 32 bears N. 3°11'29" E., 2626.76 ft. instead of N. 3°08' E., 2621.19 ft. as approved. The South 1/2 mile on the East bdy. of Sec. 32 bears N. 3°08'06" E., 2620.45 ft., instead of N. 3°08' E., 2621.19 ft. as approved.</p> <p>The 1/4 sec. cor. bet. Secs. 5 and 32, Tps. 38 and 39 N., Rs. 42 E., M.D.M., monumented with an iron pipe and brass cap properly mkd. The East 1/2 mile on the South bdy. of Sec. 32 bears S. 88°12'32" W., 2534.84 ft., instead of S. 88°12' W., 2538.36 ft. as approved.</p> <p>The witness corner for the 1/4 sec. cor of Secs. 4 and 33, Tps. 38 and 39 N., Rs. 42 E., M.D.M., was not found. The cor. of Secs 3, 4, 33 and 34, Tps. 38 and 39 N., Rs. 42 E., M.D.M., monumented with an iron pipe and brass cap properly mkd. The South bdy. of Sec. 33 was found to be N. 89°48'56" W., 5400.00 ft., instead of N. 89°48' W., 5401.44 ft as approved.</p> <p>The 1/4 sec. cor. bet. Secs. 4 and 5, T. 38 N., R. 42 E., M.D.M., monumented with a 2-1/2 in. iron pipe and brass cap properly mkd. The North 1/2 mile on the West bdy. of Sec. 4 was found to be N. 0°48'06" W., 2700.77 ft., instead of N. 0°45' W., 2695.44 ft. as approved.</p>						

	FIELD ASSISTANTS						
	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">NAME</th> <th style="text-align: left;">CAPACITY</th> </tr> </thead> <tbody> <tr> <td>Steven E. Hampton</td> <td>Instrument Man</td> </tr> <tr> <td>Dana R. Emery</td> <td>Instrument Man</td> </tr> </tbody> </table>	NAME	CAPACITY	Steven E. Hampton	Instrument Man	Dana R. Emery	Instrument Man
NAME	CAPACITY						
Steven E. Hampton	Instrument Man						
Dana R. Emery	Instrument Man						