

Subdivisions of T 31 N. R. 46 E

Sagebrush greasewood
 This line was perfectly straight as returned by me in my notes of the survey of this line. The three corners were exactly on the same straight line. The bearing as given by me in those notes N. 89° 59' W. was not quite correct.

The true bearing should have been N. 89° 52' W. The examiner in going over this line measured it very nearly correctly but the direction of his line was entirely wrong, and the three corners were in the same straight line

July 1st 1903