

Latitudes, departures and closing errors.

Line designated	True bearing	Distance	Latitudes		Departures	
			N.	S.	E.	W.
S.Bdy.sec.31	N.89°55'E.	38.27	.06		38.27	
S.Bdy.sec.31	N.89°55'E	39.95	.06		39.95	
E.Bdy.of secs. 30 and 31	N.0° 11'E	161.13	161.13		.52	
N.Bdy.sec.30	S.89°06'W.	78.94		1.15		78.94
W.Bdy.sec.30	S.0°02'E.	40.06		40.06	.02	
W.Bdy.sec.30	S.0°13'W.	40.03		40.03		.15
W.Bdy.sec.31	S.0°36'E	40.27		40.27	.42	
W.Bdy.sec.31	S.0°18'W	39.70		39.70		.21
Convergency						.03
Totals			161.25	161.21	79.18	79.33
			161.21			79.18
Error in Latitude			.04			
Error in Departure						.15

GENERAL DESCRIPTION.

This fractional township is slightly rolling, the soil a sandy clay loam from 10 to 12 ins., deep with a rocky and gravelly subsoil. The vegetation is a scanty growth of sagebrush and greasewood. There is no timber and very little water in the fractional part of this township.

Alder Creek enters the township at the southeast corner but soon sinks below the surface. There are no surface indications of mineral within secs. 30 and 31.

There are no settlers in the fractional part of this township.

H. W. Reppert
U. S. Surveyor

Alex. J. Harris
U. S. Transitman.