

LATITUDES, DEPARTURES AND CLOSING ERRORS
AND
GENERAL DESCRIPTION.

LATITUDES, DEPARTURES AND CLOSING ERRORS.

LINES DESIGNATED	TRUE BEARING	DISTANCE Chains	LATITUDES		DEPARTURES	
			NORTH Chains	SOUTH Chains	EAST Chains	WEST Chains
N.BDY. T20 $\frac{1}{2}$ N R69E	EAST ✓	476.25			476.25	
E.BDY. T20 $\frac{1}{2}$ N R69E	SOUTH	59.79		59.79		
S.BDY. T20 $\frac{1}{2}$ N R69E	N.89°58'W.	476.90	.28			476.90
W.BDY. T20 $\frac{1}{2}$ N R69E	NORTH ✓	60.04	60.04			
CONVERGENCY					.07	
		TOTALS	60.32	59.79	476.32	476.90
ERROR IN LATITUDE			.53			476.32
ERROR IN DEPARTURE						.58

GENERAL DESCRIPTION.

The land embraced within this township ranges from rolling land in the west, to broken hilly land in the extreme east. The western half of the township is covered with a scattered growth of pinon pine and juniper timber, and a medium growth of white sage, shadscale, sagebrush, and native grasses, while the eastern half of the township is covered with a medium to scattered growth of pinon pine and juniper timber and a medium growth of sagebrush, shadscale, native grasses and some white sage. The whole of the township affords good grazing for stock, but is not suitable for cultivation. The whole of this area drains in a southerly direction.

The soil changes from a fine texture of sandy, gravelly clay loam in the west to a coarser texture of the same in the east. As a whole the soil is not rich enough for cultivation.

The only people living on this township during the progress of this survey were a few men that were operating a manganese mill, located on the Independence Mill Site in the SW $\frac{1}{4}$ of the NW $\frac{1}{4}$ of section 34.

The only improvements that have been made on this township, will be found located in the near vicinity of Mike Springs, and consist of the following, one frame shack, and barn; one small log cabin; a good reservoir, with