

SUBDIVISION OF FRAC. T. 31 S., R. 66 E.

Chains

Desc.

79.80

The cor. of secs. 5, 6, 7, and 8.

Land, rough mountainous; general SE. and E. exposure.
Soil, sand, clay and gravel; granite and porphyry ledges,
4th rate.

Timber, none.

Undergrowth, scattering creosote brush, black brush,
chaparral, cat's-claw, Spanish bayonet, weeds, barrel
and cholla cacti.

Grazing, poor.

MEANDERS OF THE COLORADO RIVER THROUGH
FRAC. T. 31 S., R. 66 E.

I return to the true point for the meander cor. on N. bdy.
of frac. T. 31 S., R. 66 E., on the right bank of the
Colorado River, which is 40 lks. E. of the witness
meander cor., hereinbefore described.

Thence downstream with the meanders of the right bank of
the river, in sec. 2.

Over level land through dense undergrowth and timber.

S. 11° 41' E., 2.06 chs.

S. 40° E., 7.00 chs. Thence along rocky E. slope through
dense undergrowth.

S. 30° E., 6.00 chs.

S. 36½° E., 3.90 chs.

S. 17¾° E., 4.50 chs.

S. 35° E., 4.20 chs.

S. 25½° E., 7.70 chs.

S. 18½° E., 12.60 chs.

S. 14¼° E., 7.30 chs.

S. 12¼° E., 6.60 chs. At 4.35 chs., mouth of draw, drains
E.

S. 2¼° E., 4.40 chs.

S. 22½° E., 9.20 chs.

S. 7° E., 5.10 chs.

S. 5½° W., 4.20 chs.

S. 27° W., 1.10 chs. The meander cor. of secs. 2 and 11,
hereinbefore described.

Land, level to rolling.

Soil, silt river bottom, and gravelly clay bank, 1st and
2nd rate. Timber, cottonwoods on S. 10 chs.

Undergrowth, willows and arrow-weed.