

SUBDIVISION OF T. 19 N., R. 35 E.

Chains

- S. $0^{\circ} 04'$ E., on true line bet. secs. 5 and 6.
 Over nearly level rolling bench and flood plain through undergrowth. General ascent of gentle NW. slope 110 ft. to sec. cor.
- 8.60 Wash, 15 lks. wide, 4 ft. deep, drains W.
- 27.20 Watercourse, drains W.
- 33.60 Old road, bears E. and W.
- 40.12 Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, and in small mound of stone, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.
- $\frac{1}{4}$
 S6 | S5
 1932
- raise a mound
- of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.
- 49.80 Draw, drains N. 60° W.
- 67.00 Watercourse, drains N. 60° W.
- 80.12 The cor. of secs. 5, 6, 7, and 8.
- Land, nearly level rolling bench and flood plain.
 Soil, sand loam, clay, gravel.
 Timber, none.
 Undergrowth, shadscale, sagebrush.
 General drainage, NW.
 Grazing, fair.

GENERAL DESCRIPTION

This township is generally mountainous except for the extreme northwest corner; the elevation varies from approximately 6500 feet on the highest mountains in the southeastern portion to about 4000 feet in the rolling plains area in the northwestern portion. The general drainage is northwesterly.

The higher mountain slopes are covered with a moderately heavy stand of scrub pinon pine and juniper timber with some willow and aspen timber along the lower reaches of Bench creek canyon in the SE. corner and along Horse Creek in the NE. portion. The balance of the township is covered with a medium dense growth of desert type undergrowth with sagebrush predominating. The higher slopes afford very good grazing.

One unimproved road enters the township on the S. bdy. a short distance west of the cor. of secs. 32 and 33 and following a circuitous route to the north, northwest, northeast and southeast terminates at a small area of the only tillable ground in the township situated along Horse Creek in Section 11. An area of about 80 acres was fenced and, at time of survey, was being cultivated and developed into hay fields. A limited supply of water from Horse Creek seems to preclude additional cultivation in this area.

Several old roads were noted in the southwestern area leading to mining properties which were active during the period of about 1905 to 1910. Extensive workings in past years is evident in this portion of the township but none were operating at the time of survey. It is reported that gold and silver were the principal minerals.