

DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BDY. OF
T. 13 N.; R. 29 E.

Chains

as described in the official record.

Alongside of old post,

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

S32
 $\frac{1}{4}$ —————
S5
1936

Deposit a quart of broken glass at base of post.

80.10

The original corner of secs. 5, 6, 31, and 32, which is a cottonwood post, 4 ins. sq., 12 ins. above ground, properly marked and witnessed as described in the official record.

Alongside of old post,

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for corner of secs. 5, 6, 31 and 32, with brass cap mkd.

T13NR29E
S31 S32
+
S6 S5
T12N
1936

Deposit a quart of broken glass at base of post.

Land, rolling.

Soil, sandy; 3rd rate.

Undergrowth, greasewood, shadscale and sagebrush.

Timber, none.

Grazing, poor.

N. 89° 52' W., on true line between secs. 6 and 31

Over gently rolling land through medium dense undergrowth.

9.50

Top of bench, bears NW. and SE.; desc. 20 ft. over SW. slope to the 23.20 ch. pt.

19.80

Graded dirt road, bears NW. and SE.

22.92

Center line of irrigation ditch, 10 lks. wide, 2 ft. deep, flows SE.

23.20

Base of bench, bears NW. and SE.; continue over nearly level bottom land.

40.10

The original $\frac{1}{4}$ sec. corner, which is a pine post, 4 ins. sq., 14 ins. above ground, properly marked and witnessed as described in the official record.

Alongside of old post,