

RESURVEY OF E. BDY. T. 46 N., R. 31 E.

Chains	<p>raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, E. of cor.</p>			
39.66	<p>The cor. of secs. 1, 6, 7, and 12, an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record.</p> <p>As this now becomes the cor. of secs. 1 and 12, T. 46 N., R. 31 E. only, I remark the brass cap to read as follows,</p> <div style="text-align: center;"> <p>T46N</p> <p>R31E R32E</p> <table style="margin: auto;"> <tr> <td>S1</td><td rowspan="2">S7</td></tr> <tr> <td>S12</td></tr> </table> <p>1923</p> </div>	S1	S7	S12
S1	S7			
S12				
25.00	<p>N. $0^{\circ} 14'$ E., along the E. bdy. of sec. 1 (S. $\frac{1}{2}$ mile)</p> <p>A branch of Wilder Creek, 2 lks. wide, 2 ins. deep, course S. 70° W.</p>			
27.27	The closing cor. of secs. 6 and 7, hereinafter described.			
39.81	<p>The $\frac{1}{4}$ sec. cor., an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.</p> <p>North, along the E. bdy. of sec. 1 (N. $\frac{1}{2}$ mile)</p>			
22.30	Ridge, bears W. and N. 80° E., desc. N. slope.			
27.46	<p>A point, 40.00 chs. N. of the closing cor. of secs. 6 and 7.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.</p> <div style="text-align: center;"> <p>$\frac{1}{4}$S6</p> <p>1938</p> </div>			
39.00	<p>raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, E. of cor.</p> <p>Wash, course W.</p>			
51.53	The closing cor. of T. 46 N., Rs. 31 and 32 E., an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record.			
	<p>Dependent Resurvey of a portion of the Subdivisions of T. 46 N., R. 32 E.</p> <p>Reestablishment of the survey executed by G. W. Garside and C. S. Preble, U. S. Deputy Surveyors in 1875.</p> <p>Extensive retracements and exhaustive search was made for evidence of the original corners. The positions of the cors. of secs. 19, 20, 29 and 30 and 20, 21, 28 and 29, and the $\frac{1}{4}$ sec. cors. of secs. 20 and 29, 28 and 33 and 33 and 34, and the standard cor. of secs. 33 and 34 were recovered. No others could be found.</p> <p>The procedure hereinafter followed was authorized by Commissioner's telegram dated August 20, 1937, approving district cadastral engineer's letter dated August 10, 1937.</p>			