

Dependent resurvey of T. 32 S., R. 66 E., M. D. M.

Chains
40.63

The corner of secs. 4 and 5, marked by the 1932 resurvey monument, an iron post, 2 ins. diam., firmly set and mkd. and witnessed as described in the official record.

Land, rolling and mountainous.

Soil, sandy, gravelly and rocky; 3rd and 4th rate.

Timber, none.

Undergrowth, creosote brush, cactus and scrub mesquite.

Grazing, poor.

Meanders of the Colorado River through a portion of
T. 32 S., R. 66 E., M. D. M.

From point for the meander corner of fractional secs. 33 and 34, which is 0.56 chs. South of the witness corner monument.

Thence upstream with the meanders of the right bank of the river in sec. 34.

Over silt bottom land, through dense undergrowth and scattering timber, along top of bank, 10 ft. high.

S. 89° 00' E., 17.40 chs.

S. 88° 30' E., 16.60 chs.

S. 89° 15' E., 18.70 chs.

N. 88° 30' E., 15.50 chs.

N. 85° 54' E., 11.85 chs. Point for the meander corner of fractional secs. 34 and 35, which is 0.50 chs. South of the witness corner monument.

Land, level.

Soil, clayey silt; 2nd rate.

Timber, willow and mesquite.

Undergrowth, arrow weed, scrub mesquite and willow brush.

Grazing, poor.

Thence in sec. 35.

Over level land through dense undergrowth and scattering willow and mesquite timber, along bank 10 to 12 ft. high.

N. 81° 00' E., 6.50 chs.

N. 87° 45' E., 11.60 chs.

N. 83° 45' E., 11.00 chs.

N. 78° 30' E., 11.30 chs.

N. 77° 30' E., 7.90 chs.

N. 68° 37' E., 2.77 chs. Point for the meander corner of fractional secs. 26 and 35, which is 2.60 chs. east of the witness corner monument.

Land, level.

Soil, clayey silt, 2nd rate.

Timber, willow and mesquite.

Undergrowth, arrow weed, willow brush and scrub mesquite.

Grazing, poor.
