

Dependent Resurvey of a
Portion of E. Bdy., T. 17 N., R. 63 E.

Chains

From this cor., U. S. C. & G. S. triangulation station Ely bears
S. 53° 35' E.

40.13 Point for the $\frac{1}{4}$ sec. cor. of secs. 13 and 18, at proportionate
distance; there is no remaining evidence of the original cor.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the
ground, with brass cap mkd.

$$\begin{array}{c} \frac{1}{4} \\ | \\ S13 | S18 \\ 1955 \end{array}$$

Deposit broken glass alongside the iron post, 12 ins. below
the surface of the ground.

From this cor., U. S. C. & G. S. triangulation station Ely bears
S. 40° 02' E.

60.185 Point for the N 1/16 sec. cor. of secs. 13 and 18, at proportionate
distance.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the
ground, with brass cap mkd.

$$\begin{array}{c} N 1/16 \\ | \\ S13 | S18 \\ 1955 \end{array}$$

Deposit broken glass alongside the iron post, 12 ins. below
the surface of the ground.

80.26 Point for the cor. of secs. 7, 12, 13 and 18, monumented with a
cedar post, $1\frac{1}{2}$ ins. diam., 24 ins. long, firmly set in a mound of
earth, mkd. and witnessed as described in the official record.

At the corner point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the
ground, with brass cap mkd.

$$\begin{array}{c} T17N \\ R63E R64E \\ \hline S12 | S 7 \\ S13 | S18 \\ 1955 \end{array}$$

Reset the cedar post alongside the iron post.

Deposit broken glass alongside the iron post, 12 ins. below
the surface of the ground.

Land, level.

Soil, sandy and gravelly loam.

Timber, none; undergrowth, scattered sagebrush.

Dependent
Resurvey of a Portion of the South Boundary of T. 17 N., R. 63 E.

Reestablishment of the Survey Executed by
Monroe and Bateman, Deputy Surveyors, in 1871-72.
From the cor. of Ts. 16 and 17 N., Rs. 63 and 64 E., monumented with
an iron post, 3 ins. diam., firmly set as hereinbefore described.