Dependent Resurvey, Subdivision, T. 25 N., R. 42 E.

Chains

Land, nearly level. Soil, loam.

Vegetation, sagebrush and shadscale.

The point for the & sec. cor. of sec. 5 is at midpoint and on the N. bdy. of the Tp.

به با تحلی دی د بیشت م کینا به بید و تحلی

At the cor. point

- c 1 . L. Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T25N R42E 1959

From the above point the original standard cor. of secs. 32 and 33, T. 26 N., R. 42 E., now an angle point, bears S. 89° 48° E., 4.63 chs.

The point for the 2 sec. cor. of sec. 6 is at proportionate dist., and on the N. bdy. of the Tp.

At the cor. point

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, 

> T25N R42E , 1959

From the above point the original standard cor. of secs. 31 and 32, T. 26 N., R. 42 E., now an angle point, bears E. 4.75 chs.

## General Description

The land within the dependently resurveyed portion of T. 25 N., R. 42 E. is level to nearly level with the following exceptions: low hills along the south three miles of the east boundary and on the south boundary, rough hills on the south three miles of the west boundary, and rough hills in the interior of sections 18, 20, 28 and 33. The drainage is northeast, the main channel being the Reese River that is sometimes dry in drought years. The river enters the township near the southeast corner of section 36, meanders northerly, and leaves near the 1/2 section corner of section 1. The elevation varies from about 4,900 feet above sea level in the valley, to 5,700 feet above sea level in the hills.

The soil is loam in the valley, gravel and rocks in the hills, with undercover of sagebrush and shadscale.

There are three county roads, one of which enters near the east 1/2 corner of section 12 and exits near the west 4 corner of section 18; another enters near the northeast corner of section 36 and intersects the above mentioned road near the center of section 17; the third road enters near the northeast corner of section 6 and exits at a point 22.20 chains N. 1° 01' E. of the southwest corner of section 6.

There is considerable homestead activity in this township. Almost the whole valley has been covered by homestead entries since the first good water well was drilled in 1959.

الد. : فللله و الملك الله وقول المالية الإرام في المالية الم

There are no apparent mineral deposits within the township.