

Limited Dependent Resurvey,
T. 32 S., R. 66 E., M. D. M., Nevada

Chains

in the official record.

N. 89° 47' E., beginning new measurement.

Continue descent into bottom; desc. 60 ft. over E. slope.

2.50 Base of bench land, bears N. and S.; thence over level bottom land.

10.49 The point for the witness meander cor. of secs. 13 and 24, which is marked by an iron post, 1 in. in diam., set, mkd. and witnessed as described in the official record.

10.99 The right bank of the Colorado River, bearing S. 15° 45' S. and N. 15° 15' E., and true point for the meander cor. of secs. 13 and 24, falls on steep insecure silt bank where a monument cannot be maintained. The witness meander cor. was set as described above.

Land, rolling bench and level bottom.

Soil, shallow sand and silt.

Timber, none.

Undergrowth, creosote bush, cacti and arrowweed.

Note: There has been no appreciable change in the position of the right bank of the Colorado River, since the date of the original surveys and the resurveys of 1947, in front of secs. 24, 26, 34 and 35, which sections are public lands withdrawn for reclamation purposes. Consequently, the right bank in those sections was not remeandered.

Meanders of the Right Bank
of the Colorado River,
in Sec. 32.

From the true point for the meander cor. of secs. 5 and 32, on S. bdy. of Tp.

Thence with the meanders of the right bank of the Colorado River, upstream.

In sec. 32.

N. 84° 43' E., 5.24 chs.

N. 39° 44' E., 7.10 chs.

N. 19° 18' W., 3.26 chs.

N. 56° 41' W., 5.50 chs.

N. 14° 07' E., 9.51 chs.

N. 31° 57' E., 9.54 chs.

N. 46° 17' E., 4.40 chs.

N. 67° 38' E., 5.40 chs.

N. 76° 33' E., 8.10 chs.