## DEPENDENT RESURVEY OF A PORTION OF THE EAST BOUNDARY, T. 31 N., R. 56 E., MDM, NEVADA

	T. 31 N., K. 36 E., MUM, NEVADA
CHAINS	At the corner point
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, with brass cap mkd.
	T31N R56E R57E S 12 S 7 S 13 S 18
	1974
	Reset the wooden post and steel fence post alongside the iron post.
	N. 0° 24' E., bet. secs. 7 and 12.
	Over rolling land, through scattered sagebrush and native grass; asc. over SE. slope.
19.20	Top of ascent, edge bears E. and W.; over nearly level bench land.
39.84	Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T31N R56E R57E
	s 12 s 7
	1974
	Set a juniper post, 5 ft. long, alongside the iron post.
79.68	The cor. of secs. 1, 6, 7 and 12, monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set and exposed 12 ins. above the ground, with brass cap mkd. RWM + SON T31N R56E R57E S1 S6 S7 S12 1964. This monument was established by R. W. Millard and Son, Registered Engineers and Land Surveyors; an unmarked stone, 15X5X3 ins. was found at this point. It is harmoniously related to other existing original corners and is
	locally recognized and is accepted as a careful and faithful perpetuation of the position of the original corner. This monument meets the standars set by the Bureau and was not remonumented. Add the marks BLM and 1983 to the brass cap.
	N. 0° 32' E., bet. secs. 1 and 6.
	Over gently rolling land, through scattered sagebrush and native grass.
3.10	Wash, 5 lks. wide, 1 ft. deep, drains N. 65° W.