Expenditure of Five Hundred Dollars.

I certify that the value of the labor and improvements, placed thereon by the claimants and his grantors, is not less than Five hundred dollars for each location and that said improvements consist of;

No.1 A shaft, the center of the mouth of which bears from cor.No.2,Northern lode of this survey S.81 deg.49 mins.E,397.2 ft.,in hard rock 4 x 6x19 ft deep

Value----------$250.00

No.2 A tunnel, the mouth of which bears from cor. No.2 Northern lode of this survey S.81 deg.49 mins. E,394 ft., in solid rock 4 x 6 ft. From mouth, tunnel runs S.6 deg. 53 mins. E, 83 ft. to face.

Value----------$830.00

No.3 A shaft, the center of the mouth of which bears, from cor.No 3 Brileant lode of this survey S.59 deg..06 mins. W,417 ft. in hard rock 4 x 6x25ft deep.

Value----------$375.00

No.4 A shaft, the mouth of which bears, from cor. No.3 Brileant lode of this survey, S.73 deg.51 mins. W., 622.2 ft.in hard rock,4 x 6 X 22 ft. deep.

Value----------$330.00

No.5 An open cut, the mouth of which bears, from cor. No.3, Brileant lode of this survey,S.73 deg.51 mins. W,642.2 ft. From mouth cut runs S.45 deg.E.5 x 6 x 16 ft.

Value----------$25.00

Other Improvements.

There are none.

Instrument.

This survey was made with a Berger & Son's light mountain transit No.4. The courses were deflected from the true meridian as determined by direct solar observations. The distances were measured with a five hundred foot steel tape

Description of Corners.

The 1/4 sec.cor. bet.secs. 14-15,T 16 N.,R.62 E, Mount Diablo base of meridian is a cedar post 4 X 4 X 14 ins. above ground, marked 1/4-14-15 on east side.

Cor. No. 2, survey No.2768 American lode, identical with Cor.No.3,Survey No.2378 Kellinsko Hill lode, is a pine post, 4 ft.long 4 ins.square firmly set in the ground extending 3 ft.above mound of earth scribed 2-2768,and 3-2378.

Cor.No.2, Rising Sun lode (unsurveyed) is a pine post, 4 ins. square, firmly set in ground, extending 3 ft above mound of earth, marked Rising Sun No.2.

NOTE: The disagreements between these field notes and the location certificates with regard to the position of the discovery points, are due to errors in the latter.