T20N R28E

Re-Survey of a portion of the Exterior boundaries of T20N R28E.

In the subdivision of this Township I commenced by running North on a trail line on the East boundary of Sec 36, and at 40 ch could find no evidence of a 1/4 Sec Cor:

at 80 ch found a Sec Cor post lying upon the ground 30 links S and 1.50 ch West of point, I therefore continued my line North and found none of the corners standing in place and although diligent search was made at each 40 and 80 chains