Resurvey of E. bdy. T 33 N, R 41 E

Chains.	
46.50	Mountain spur, slopes S. E.
53.70	Ravine, course S. E.
55.60	Mountain spur, slopes S. E.
57.88	Ravine, course S. E.
69.40	Mountain spur, slopes S. E
76.40	Ravine, course S. E.
84.66	The cor. of Tps. 33 and 34 N, Rs. 41 and 42 E re-established by me Oct. 1910

Whence a mining shaft about 70 feet deep bears S 62°30' W, 4 chs. dist. There is a good looking vein, several feet wide, showing in this shaft. The vein has a general northerly and southerly course. There are several tons of ore on the dump.

Land, mountainous.

Soil, rocky 3rd and 4th. rate.

S. 40.16 chs. is rolling mountains covered with wash.

N 44.46 chs. is more steep and rugged. Much quartz float scattered about and good mineral indications. Good growth sagebrush, little grass, no timber. Slopes S. E.

April 11, 1911.

Subdivision of T 33 N R 41 E

April 12, 1911.

Since both the S. and E. bdys. are out of limits in alinement and distance it will be necessary to establish a sectional guide meridian and a sectional correction line. I begin at the cor. of secs. 1, 2, 35 and 36 on the N. bdy and run S. on a random line; and also from the cor. of secs. 25, 30, 31 and 36 on the W. bdy. I run a random line E. At the point of intersection of these two random lines I establish the cor. of secs. 25, 26, 35 and 36 as follows: