Chains

Timber, none.
Undergrowth, scattered creosote brush and cacti.

Meanders of the Right Bank
of the Colorado River,
T. 33 S., R. 66 E.

In 1958-60, the Colorado River was rechannelized in this vicinity by the Bureau of Reclamation. This work was done wholly within the bed of the river in this reach and did not cross any fast lands. The river as rechannelized is contained within artificial banks backed by a secondary levee system.

The following surveys are those of the meanders of the right bank of the river as it existed at the time of the rechannelization. In places the present river is approximately one-half mile from the old bank and in other places the two banks are coincident. The old bank is well defined, being for the most part sharp and distinct. The abandoned bed is partially barren and partially covered by a new growth of arrowweed and salt cedar.

From the true point for the meander cor. of sec. 21, only on the northeasterly boundary of Fort Mohave Indian Reservation, as hereinbefore described.

Thence, with the meanders of the old right bank, upstream.

In sec. 21

S. 65° 36' E., 3.57 chs. To the true point for the meander cor. of secs. 21 and 22, as hereinbefore described.

Thence, in sec. 22

S. 66° 32' E., 4.29 chs.

S. 70° 42' E., 2.14 chs.

S. 88° 33' E., 2.83 chs.

N. 75° 23' E., 1.71 chs.

N. 49° 13' E., 3.76 chs.

N. 69° 53' E., 5.04 chs.

N. 83° 15' E., 2.35 chs.

S. 89° 02' E., 3.78 chs.

N. 72° 56' E., 2.71 chs.

N. 37° 11' E., 6.48 chs.

N. 26° 40' E., 1.70 chs.