Resurvey of a Portion of the Subdivisions
of
T. 24 S., R. 56 E.

chains

Thence,

West on a random line bet. secs. 25 and 36.

40.00 Find no trace of ¼ sec. cor.; set temp. cor.

80.00 Find no trace of cor. of secs. 25,26,35 and 36; set temp. cor.

Continue line and measurement bet. secs. 26 and 35.

120.00 Find no trace of ¼ sec. cor.

120.17 A point 144 lks. S. of the clos. cor. of frac. secs. 26 and 35, hereinbefore described.

From a point 66 lks. E. of the temp. cor. of secs. 25,26, 35 and 36.

South on a random line bet. secs. 35 and 36.

39.81 A point 26 lks. W. of the clos. cor. of frac. secs. 35 and 36, hereinbefore described.

Return to the point 66 lks. E. of temp. cor. of secs. 25, 26, 35 and 36.

Thence, north on a random line bet. secs. 25 and 26.

40.00 Find no trace of ¼ sec. cor.; set temp. cor.

81.68 A point 86 lks. E. of the cor. of secs. 23,24,25 and 26.

From the cor. of secs. 25,30,31 and 36, on E. bdy. of Tp.

N.88°50'W., on true line bet. secs. 25 and 36.

Over rolling desert land, thru scattering undergrowth.

Over low sand hills.

37.00 Leave sand hills; continue over level land.

39.68 Set an iron post 3 ft. long 1 in. diam., 27 ins. in the ground, with a quart beer bottle deposited at the base, for ¼ sec. cor., with brass cap marked

¼ S 25
S 36
1932

dig a circular trench 5 ft. diam.and pile the dirt around post to top.

79.36 At this point; determined by double proportion:
Set an iron post 3 ft. long 2 ins. diam., 27 ins. in the ground, for cor. of secs. 25,26,35 and 36, with brass cap marked

T 24 S R 56 E
S 26 | S 25
S 35 | S 36
1932

deposit a quart beer bottle alongside post, at base, and dig a circular trench 5 ft. diam., piling the dirt around post to top.

Land, low sand hills and level desert.
Soil, sand and shadscale, 2d and 3d rate.
Undergrowth, creosote brush, sage and cacti.