S Boundary T 32 N R 20 E M.D.M

East on a true line between Secs 2 and 35
Var 17°15' East

4000 set a charred post in mound with pits as per instructions for 1/4 sec Cor

8000 Set a charred post in mound with pits as per instructions for Cor to secs 1-2-35 and 36

Land level soil 2nd rate

Sagebrush and Greasewood.

East on a true line between Secs 1 and 36
Var 17°15' East

4000 Set a charred post in mound with pits as per instructions for 1/4 sec Cor

8000 Set a charred post in mound with pits as per instructions for Cor to Townships 31 and 32 North Ranges 20 and 21 East

Land level soil 2nd rate. Greasewood.