2. 128 E.B. Rt

# Exteriors T. 36 N. R. 54 E. M.D.M.

Start

Having examined the surveyed portions of the exteriors of this township & found most of the corners defaced & several missing ~~&xxxx~~ I re-survey the same as follows.

At 7 a.m. Sept. 22nd 1894 I set over the S. E. corner of T. 36 N R. 54 E & test the adjustment of my transit which I find to be correct.

I now find the variation of the meridian established by me last night to be 17° 30' E.

Hence I run,

N on E bdy of sec. 36

Var. 17 30 E.

| | |
|---|---|
| 250 | rav. N W. |
| 1300 | Ridge N W. |
| 2300 | Rav. N W. |
| 4000 | Ridge E & W. Old 1/4 sec. cor. which |