Resurvey of the south boundry of T34N, R40E, south of secs. 34, 35 and 36.

Here/ chains	
41.75	W. bank of dry wash, course N.E.
42.26	E. bank of same dry wash.
68.80	Road, course N.E. and S.W.
80.00	The old cor. for secs. 1, 2, 35 and 36. I destroy all traces of this cor. and its accessories, and reestablish it at the same point as follows: Set an iron post filled with cement and surmounted by a brass cap, 3 ft. long, 3 ins. in diameter, 2 ft. in the ground for the cor. of secs. 1, 2, 35 and 36, marked on top,

T34N
R40E

S35	S36
S2	S1

T33N
1910

dig pits 18 X 18 X 12 ins. in each sec. 5½ ft distant; and raise a mound of earth 4 ft. base, 1½ ft. high W. of Cor.
Land level.
Good soil, derived from the disintegration of volcanic and granite rocks, from 2 ft. to 6 ft. deep, containing some gravel. Good growth of sage brush, little grass, and no timber.

Thence I run on a true line, N 89° 13' E, between secs. 1 and 36. Over level land.