E. bdy. of T 26 N, R 26 E.

Chains.

N. bet. secs. 7 and 12.
Over level land.
3.30 Wash, course N. E.
12.20 Wash, course E.
40.00 Set an iron post 3 ft. long, 1 in. diam. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. with brass cap mk'd.

S 12 $\frac{1}{4}$ | S 7
1911

dig pits 18 x 18 x 12 ins. N. and S. of post, 3 ft. dist. and raise a mound of earth 3 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high W. of cor.
43.00 Small wash, course E.
55.15 Small wash, course S. E.
77.20 Large ravine, course N. E
80.00 Set an iron post, 3 ft. long, 3 ins. diam. 24 ins. in the ground for cor. of secs. 1, 6, 7 and 12; with brass cap mk'd.

T 26 N

R 26 E	R 27 E
S 1	S 6
S 12	S 7

1911

dig pits 18 x 18 x 12 ins. in each sec. 5 $\frac{1}{2}$ ft. dist. and raise a mound of earth 4 ft. base, 2 ft. high W. of cor.
Land, level.
Soil, good, rich sandy desert loam. 1st. rate. Good growth, short sage-brush, little grass, no timber.
Slopes N. E.

N. bet. secs. 1 and 6
Over level land.
27.00 Wash, course E.