Chains

TR. 47, hereinbefore described.

Thence

East on line 3-4 of TR. 48.

20.00 Set an iron post 3 ft. long, 1 in. diam., 26 ins. in the ground for cor. No. 4 of TR. 48, identical with cor.No. 3 of TR. 49, with brass cap mkd.

```
T16S R56E
TR48 | TR49
   4 | 3
  ---------
     S 16
    1917
```

Thence

North on line 4-5 of TR. 48.

20.00 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground for cor. No. 5 of TR. 48, identical with cor.No. 2 of TR. 49, with brass cap mkd.

```
T16S R56E
TR48
   5 ------
        | 2
        | TR49
    1917
```

Thence

East on line 5-6 of TR. 48 in conflict with Tract 45 Franklin Eddy

20.00 Set an iron post 3 ft. long, 1 in. diam., 26 ins. in the ground for cor. No. 6 of TR. 48, identical with cor.No. 1 of TR. 49, with brass cap mkd.

```
T16S R56E
TR48 |
   6 |  S 16
  ---|
   1 |
TR49 |
     1917
```

Thence

North on line 6-1 of TR. 48 in conflict with Tract 45 Franklin Eddy.

20.00 To cor. No. 1 of TR. 48, or point of beginning.