Resurvey of the 86th. Mile of the Utah-Nevada boundary

Chains

62.23 The original position for Monument No. 86, which is identified by a large mound of earth, and the original bearing trees, which are in good condition. The original corner post has been carried off for fire wood, probably, as there are indications of recent chopping in the immediate vicinity. I perpetuate the position of the original monument, as follows,

Set an iron post, 3 ft. long, 3 ins. in dia., 24 ins. in ground, with brass cap marked,

N | U
86
MILE
1918 ; from which,

A cedar, 12 ins. in dia., bears East, 38 lks. dist, marked, UTAH BT

A cedar, 10 ins. in dia., bears S 60°W., 45 lks. dist., marked, NEVADA BT

Land, rolling.

Soil, 4th rate, rocky and sandy gravel

Timber, none.

Undergrowth, sage brush, dense juniper.

Retracement of the Fifth Standard Parallel North.

From the original re-established Standard Closing corner of T.26 N., R . 70 E., on the Utah-Nevada boundary, previously described,

West, on a random line on the south boundary of T. 26 N., R. 70 E., searching for original corners at record distance,

43.20 No trace of the original standard ¼ sec.cor.

83.20 No trace of the original standard cor. of secs. 33 and 34

123.20 No trace of the original standard ¼ sec. cor.

163.20 No trace of the original standard cor. of secs. 32 and 33.

203.20 No trace of the original standard ¼ sec.cor.