Retracement of the N. bdy. of T. 42 N., R. 51 E.

Chains	
	accepted as the true corner point. The true course of
	this line is S.89°45'E., and the length is 39.94 chs.

	East, along the N. bdy. of sec. 3,
40.00	No trace of original corner.
80.06	Fall 21 lks. N. of the cor. of secs. 2, 3, 34 and 35,
	hereinafter described.
	The true course of the this mile is S.89°51'E., and the
	length is 80.06 chs.

	East, on random line, on the N. bdy. of sec. 2.
40.11	Fall 9 lks. N. of the old ¼ sec. cor. of secs. 2 and 35,
	hereinafter described. The true course of this half
	mile is S.89°52'E., and the length is 40.11 chs.
	From the ¼ sec. cor. with continuous measurement.
80.20	Fall 17 lks. S. of the cor. of secs. 1, 2, 35 and 36,
	hereinafter described. The true course of this line
	is N.89°45'E., and the length is 40.09 chs.

	East, on random line, on the N. bdy. of sec. 1.
39.53	Fall 14 lks. N. of the old ¼ sec. cor. of secs. 1 and 36,
	hereinafter described. The true course of this line
	is S.89°48'E., and the length is 39.53 chs.
	From the old ¼ sec. cor. with continuous measurement.
79.53	After diligent search, I find no trace of the old cor. of
	Ts. 42 and 43 N., Rs. 51 and 52 E.
	Set temp. point.

	Retracement of a portion of the N. bdy. of T. 42 N.R. 52 E.

	From the temp. cor. of Ts. 42 and 43 N., Rs. 51 and 52 E.
	set 40.00 chs. East of the old ¼ sec. cor. of secs. 1
	and 36,
	East, on blank line, on the N. bdy. of Tp.,
171.00	Fall 13.86 chs. S. of the cor. of secs. 4, 5, 32 and
	33, which is described by the Surveyor General for