Chains	
	Over nearly level land, thru scattering undergrowth.
40.02	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a bottle containing cor. description deposited at base, for the ¼ sec. cor., with brass cap mkd. ¼ S 2 / S 11 1940 No suitable accessory.
80.04	The cor. of secs. 2, 3, 10 and 11. Land, nearly level. Soil, sandy, alkaline clay; 3d rate. No timber; undergrowth, greasewood and shadscale. Grazing, poor.
	N. 0° 02' W., on true line bet. secs. 2 and 3. Over nearly level land, thru scattering undergrowth.
40.00	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for the ¼ sec. cor., with brass cap mkd. ¼ S 3 | S 2 1940 raise a mound of stone, 2 ft. base, 1½ ft. high, W. of cor.
80.00	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a bottle containing cor. description deposited at base, for the cor. of lots 1, 4, 5 and 8, with brass cap mkd. S 3 1 | 4 S 2 8 | 5 1940 No suitable accessory.
89.47	Intersect the 8th standard parallel N. Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for the closing cor. of secs. 2 and 3, with brass cap mkd. T41N R36E S34 S 3 | S 2 T40N R36E CC 1940 raise a mound of stone, 2 ft. base, 1½ ft. high, S. of cor. From this point, the standard cor. of sec. 34 and 35, bears N. 89° 00' E., 5.66 chs. dist. Land, nearly level. Soil, sandy alkaline clay; 3d rate. No timber; undergrowth, greasewood and shadscale. Grazing, poor.