

Report.

After strict search and due examination on the ground, I was unable to find any of the corners of Sec. 20 T. 21 N. R. 23 E. M. D. M. and the intersections with the lines of said sections were calculated from the Official returns of the Public Land Survey.

The S. $\frac{1}{4}$ ^{Cor} Sec. 29 T. 21 N. R. 23 E. M. D. M. is a stone 8 x 12 ins., set in a mound of stone and marked $\frac{1}{4}$ on the north face.

The Tie from Cor. No. 1, Sur. No. 2136, Gold Ledge lode, to the S. $\frac{1}{4}$ Cor. Sec. 29 T. 21 N. R. 23 E. M. D. M. was found to be S. $4^{\circ}08'$ W. 4511 ft. instead of S. $3^{\circ}21'$ W. 4532 ft. as approved; and line 5 - 1 of Sur. No. 2136, Gold Ledge lode, was found to be S. $9^{\circ}40'$ E. 595.76 ft. instead of S. $9^{\circ}40'$ E. 600 ft. as approved.

Cor. Nos. 3 and 6 Sur. No. 2575. Black Horse lode are each a pine post 4 ins. sq. 2-1/2 ft. above ground in mound of earth and stone scribed 3-2575 and 6-2575 respectively.

Cor. Nos. 1 and 4 Independence lode unsurveyed are each a pine post 4 ins. sq. 2-1/2 ft. above ground in mound of earth and stone, scribed S.E. Cor. No. 1 Independence lode, and N.E. Cor. No. 4 Independence lode respectively.