

SURVEY NO. 2735.

hills, void of timbering and other natural objects for bearings.

NOTE:- The difference between these field notes and the location certificates is due to errors in the latter.

REPORT:- After diligent search the South 1/4 Cor. Sec. 34, Tp. 28-S., R. 63-E., M.D.M. and the North 1/4 Cor. Sec. 3, Tp. 29-S., R. 63-E., M.D.M., could not be found.

The Government Section Corners reported in this Survey are described as follows:- N.E. Cor. Sec. 3, Tp. 29-S., R. 63-E., M.D.M., is a rock set in a mound of stone and earth chiseled 2 notches East, 4 notches West. The S.W. Cor. Sec. 34, Tp. 28-S., R. 63-E., M.D.M. is a reddish brown rock, 12 ins. by 6 ins. 12 ins. above the ground, chiseled 3 notches East and 3 notches West.