

4 3005 Survey No. 3005.

## Attachment.

The courses were deflected from the true meridian as determined from solar obsetvations, the latitude being determined by solar obserwations at noon.

The distances were measured with 100ft. and 300 ft. steel tapes.

## REPORT.

Report. The corner of Secs. 2 and 3 on north boundary of T. 30 N. R. 34 E.; and corner of Secs. 26, 27, 34 and 35, T. 31 N. R. 34 E. M. D. B. and M. are the only corners of the public survey near the Bloody Canyon Lode that are standing although I made diligent search for the corner of Secs. 34 and 35 on south boundary of T. 31 N. R. 34 E; and for the  $\frac{1}{4}$  corner between Secs. 34 and 35, T. 31 N. R. 34 E.

Corner of Secs. 2 and 3, T. 30 N., R. 34 E. is a redwood post 2  $\frac{1}{2}$  inches square showing 2  $\frac{1}{2}$  ft. above ground scribed T. 30 N. on S., R. 34 E. on N., S. 2 on E. and S. 3 on W. faces with 2 grooves on E. and 4 grooves on W. faces and pits E. W. and S. of post.

Corner of Secs. 26, 27, 34 and 35 T. 31 N., R. 34 E. is a granite stone 8 x 8 ins. showing 8 ins. above ground, marked with one notch S. and two notches on E. edges. No mound or pits remaining.

There are no intersections returned with the Section line between Secs. 34 and 35; T. 31 N., R. 34 E. M. D. B. and M. as a line drawn between the N. E. Cor. of Sec. 34 and a point 2.96 chains west of the Cor. of Secs. 32 and 3 T. 30 N., R. 34 E. M. D. B. and M. will not be intersected by the lines of this survey. It will not be intersected by the lines of this survey.

## INDUSTRIES

This area has suffered a great change over various years. The timber and mining industries have been replaced by agriculture and ranching.