

(17)

Note:- The disagreements between these field notes and the amended location certificates are due to errors in the latter.

The corners of adjoining and conflicting claims were found to be as follows:-

Cor.No.2 Sur.No. 76 Hirschell lode is a pine post 4 ins. square 2.5 ft. above ground with mound of stone scribed No.2 U.S.S 76.

Cor.No.3 is a pine post 4 ins. square 2.5 ft. above ground with mound of stone scribed No.3 U.S.S.76.

Cor.No.4 is a pine post 4 ins. square 3 ft. above ground with mound of stone scribed No.4 U.S.S.76

No corners of any other conflicting claims could be found and the connections to them were obtained through a connection to the center of the discovery or working incline shaft of Sur.No.79 the Gov.Seymour lode, whence Cor.No.1 of said lode bears N.7 15'W. 316.ft. as approved. The said incline shaft was located and identified by several of the older residents of the district who have been familiar with its position since it was first sunk.

U.S.Mineral Monument No.1 is a pine post 4 ins. square 3 ft. above surface located at summit of rocky point with mound of stone scribed U.S.S.M.M.No.1

The W. 1/4 Corner of Sec.19- T.19 N.- R. 44 E. is a gray granite stone 8x10x12 ins. above ground chiseled 1/4 S. on the West side.

Sec. 64, 1908.