

Survey No. 3957.

Dimmick No. 2 and Dimmick Fraction lodes as to the courses and lengths of the boundary lines and lode lines, are due to errors in the latter.

REPORT.

All lines of these surveys of the Dimmick No. 1, Dimmick No. 2 and Dimmick Fraction lodes and the tie lines between the same and the tie lines to conflicting surveys, and the respective ties to the N.E. Cor. Sec. 24, T. 6N., R. 49 E., Mt. Diablo B. and M., were made direct upon the ground.

N.E. Cor. Sec. 24, T. 6 N., R 49 E., Mt. Diablo B. and M. is a limestone stone showing 8 ins. above the surface of the ground chiseled with two notches on the south, and four notches on the north edges. After diligent search this is the nearest corner of the public survey that could be found with reference to any of the corners of this survey.

Cors. No. 1, 2, 7, and 8 Sur. No. 39 Lafayette lode are posts 4ins. square showing 2.5 ft. above the ground in mound of earth and stone, scribed with their proper number of survey and corner. Cor. No. 1 Sur. No. 2123 G.F.Mine lode is a pine post, 5ins. square, showing 3.0 feet above the surface of the ground in mound of earth and stone scribed, 1-2123.

I find the bearing of line 1-2 Sur. No. 39 Lafayette lode to be S. 62° 39' E. instead of S. 62 $\frac{1}{4}$ ° E. as approved.

I find the bearing of line 7-8 Sur. No. 39 Lafayette lode to be N. 62° 43' W. instead of N. 62 $\frac{1}{4}$ ° W. as approved.

I find line 8-1 Sur. No. 39 Lafayette lode to be N. 27° 19' E. 245.52 ft. instead of N. 27 $\frac{3}{4}$ ° E. 246. ft. as approved.

NOTE: - The discrepancies between the field notes and the location certificates of the Dimmick No. 1,