REPORT

run upon the ground, and the several corners established by means of offsets from the lode lines. The tie line of Cor. No. 1 Golden Treasure lode was run upon the ground, the other ties are traverse ties. The SE Cor. of Sec. 34 T. 40 N. R. 51 E. M. D. M. is a gas pipe about 12 ins. in diameter, 18 ins. above ground set in a mound of earth and stone. This corner is in the town of Tuscarora, the original corner having been destroyed, the corner accepted is this iron pipe.

The 4 Cor. between Secs. 34-35 T. 40 N. R. 51 E. M. D. M. is missing

Cors. Nos 3 and 4 Survey No. 1840 Blossom lode are missing . 12 3 and . 23 and . 34 and . 35 and . 36 and . 37 and . 38 and . 38

Cor. No. 3 Survey No. 1838 Frank lode is missing Cors. No. 3 and 4 Survey No. 1840 Comfort lode are missing.

I could no corners on Survey No. 37B Young America Millsite, Survey No. 39 Centennial Quartz lode, Survey No. 40 Oreade lode, Survey No. 41 Virginia lode Survey No. 44B Grand Prize lode, Survey No. 50

Jeannette lode, Survey No. 45 Buckeye lode or Survey No. 51 Rising Sun lode.

Surveys No. 39 Centennial Quartz lode, No. 40 Oreade lode, No. 41 Virginia lode and No. 44B Grand Prize lode were never patented and the ground has been located several different times.

The calculations are made from the tie lines as returned to the Surveyors General's office for the old surveys.
Claimants of the above Mineral Survey Numbers are unknown.

.equi lesta .di 008