

## REPORT

The boundary lines of this survey were run upon the ground.

The tie line was run upon the ground.

The SE Cor. of Sec. 13 T. 45 N. R. 63 E. M. D. M. is a quartz rock 8X8 ins. 12 ins. above ground with 3 grooves on the north face and 3 grooves on the south face.

The  $\frac{1}{4}$  Cor. on the South boundary of Sec. 13 T. 45 N. R. 63 E. M. D. M. is missing.

Cor. No. 4 Survey No. 1972 Valley View lode was a wooden post but has been replaced with a stone corner as described herein.

Cors. Nos. 3 and 4 Survey No. 1995 Green Monster lode are rocks properly set and marked.

Cors. Nos. 1 and 2 Survey No. 1999 Reliance lode are rocks properly set and marked.

I find lines 1-2 Survey No. 1999 Reliance lode and line 3-4 Survey No. 1995 Green Monster lode correct as approved.

All the chiseling of survey No. 4016 has been obliterated.

As the only Notary Public within 60 miles of this survey was one of my assistants it was necessary for me to take their affidavits.