

Instrument, continued.

distances were measured with 650 ft. and 100 ft. steel tapes.

REPORT:

The lode line of the location embraced within this claim was run directly upon the ground and the several corners established by means of offsets from the lode line. The tie line to the W. $\frac{1}{4}$ Sec. Cor., Section 31, T.25 S., R.58 E., M.D.M., was run by a traverse and a separate report thereof submitted herewith. All other tie lines were run directly upon the ground.

The W. $\frac{1}{4}$ Sec. Cor. Section 31, T.25 S., R.58 E., M.D.M. is a post by 2 $\frac{1}{2}$ ins. by 2 $\frac{1}{2}$ ft. long, set in a small mound of stone and earth and scribed, " $\frac{1}{4}$ S ". Diligent search was made for a Cor. of Sections 31, 32 and 33, T.25 S., R.58 E., M.D.M. but none could be found and identified.

Milford No.4 lode, unsurveyed:-

All corners mentioned herein are pine posts, 4 ins. square, properly set and marked with description of the corner thereon.

Milford No.5 lode, unsurveyed:-

All corners mentioned herein are pine posts, 4 ins. square, properly set and marked with a description of the corner thereon.

Addison No.2 lode, unsurveyed:-

All corners mentioned herein are pine posts 4 ins. square, properly set and marked with a description of the corner thereon.

Note:--

All discrepancies between these notes and the amended certificate of location of this lode is due to errors in said amended certificate of location.

No.2

The N.W. Cor. Addison lode, unsurveyed, reported in Sur. No. 4331 at N.40°06'W. 223.80 ft. from Cor. No.1, Ingomar lode, of said survey, and now reported at N.40°06'W. 206.18 ft. from Cor. No.4 Milford No.2 lode of this survey, identical with Cor. No.1, Ingomar lode Sur. No. 4331, has no doubt been moved since Sur. No. 4331 was made.