

None,

---

INSTRUMENT.

This survey was made with an Ainsworth Light Mountain transit. The courses were deflected from the true meridian as determined by direct solar observations. The distances were measured with a 700 ft. steel tape.

---

REPORT.

All tie lines were run directly upon the ground.

The NE. Cor. Sec. 16, T. 31 N. R. 43 E. of M. D. B. & M. is a granite stone, chiseled with three notches on east face and four notches on south face.

The  $\frac{1}{4}$  Cor. between Sections 15 and 16, T. 31 N. R. 43 E. of M. D. B. & M. is an iron post, properly set and marked.

Sur. No. 3074, Weimer Burr, Marion and Walter Earl lodes; all of the corners are pine posts, properly set and scribed with the number of the corner and survey. I find all courses and distances to be correct as reported.

Cor. Nos. 1 and 3, Surprise lode, unsurveyed, Cor. No. 4, Buena Vista lode, unsurveyed, and Cor. Nos. 3 and 4, Blossom lode, unsurveyed, are pine posts, properly set and marked with the name of the claim and the corner.