

Mineral Survey 4696

No. 318, and from which the N. $\frac{1}{4}$ Cor. of Sec. 35 T. 9 N.R. 45E. M.D.M. bears S. 51° 54' E. 32674.00 ft.

Said $\frac{1}{4}$ Sec. Corner is a granite stone 8 x 12 x 10 ins. above ground, chiseled 1/4 S. and with a mound of stone 2 ft. high along-side.

Sur. No. 38 Barcelona lode No. 1 South Extension

All corners are very old hewed 4 x 4 pine posts set in a mound of stone and properly scribed.

I find line 1 - 2 to S. 27° 44' E. 600 ft. instead of S. 27° 54' E. 600 ft. as approved, and line 2 - 3 to be N. 62° 16' E. 1488.58 ft. instead of N. 62° 06' E. 1500 ft. as approved.

NOTE: The disagreements between these field notes and the location certificates are due to errors in the latter.

Respectfully,

Edward L. Haff
U.S. Mineral Surveyor

REPORT

ALL lines and ties in this survey were run upon the ground and the courses and distances found to be as herein given. U.S. Mineral Survey No. 318 to which connections are given in this survey is a pine post 6 ins. sq. 8 ft. long set in a mound of stone 6 ft. at base and 4 ft. high, scribed U.S.M.M.