

Mineral Survey No. 4713

UNLUCKY JIM LODE (Cont'd)

No. 16 A cut the mouth of which bears from Cor. No. 3 N. $45^{\circ}30'$ W. 510 ft. 4 ft. wide extends N. $62^{\circ}30'$ W. 10 ft. to a 10 ft. face; at face of cut a tunnel 4 x 6 ft. runs N. $62^{\circ}30'$ W. 5 ft. to face on a mineralized quartz vein in dacite.

Value of cut and tunnel \$100.00

OTHER IMPROVEMENTS

None

INSTRUMENT

This survey was made with a C.L. Berger & Sons No. 2 Transit. The courses were deflected from the true meridian as determined by direct solar observations. The distances were measured with 100 and 500 ft. steel tapes.

REPORT

All lines and ties in this survey were run upon the ground and the courses and distances found to be as herein given.

The Southwest Corner of Sec. 32 T. 2 S. R. 43 E., to which connection is given, is a granite rock properly set and marked with a mound of stone 2 ft. high alongside. Sur. No. 2273 Wild Horse, Monarch, Snow Drift Fraction, and Snow Drift No. 2 lodes, all corners are pine posts 4 ins. sq. properly set and scribed. Sur. No. 2682 Bonanza lode, all corners are pine posts 4 ins. sq. properly set and scribed.

Sur. No. 3283 Wonder Lode Fraction lode, all corners are pine posts 4 ins. sq. properly set and scribed.

Sur. No. 3526 Unlucky Jim lode, all corners are pine posts 4 ins. sq. properly set and scribed.

NOTE:

The disagreements between these field notes and the amended location certificate are due to errors in the latter.