

FEET

an undivided one-fourteenth interest in their value is hereby credited to each of the lodes.

No portion of or interest in these improvements has been credited heretofore as Patent expenditure to any lode claims.

OTHER CORNER DESCRIPTIONS  
AND SUPPLEMENTAL DATA

M.S. No. 5059, M.S. No. 5060, M.S. No. 5061, and M.S. No. 5062 were surveyed concurrently.

The cor. of secs. 13, 18, 19, and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found monumented with a properly marked  $2\frac{1}{2}$  ins. brass cap showing 10 ins. above ground.

The cor. of secs. 19, 24, 25, and 30, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, has been destroyed by mining activity. The position was calculated based upon the information recorded on Record of Survey File No. 10190 of the official Records of Eureka County, Nevada, and was not remonumented at the time of this survey due to current mining activity.

The cor. of secs. 23, 24, 25, and 26, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found monumented with two witness corners as follows:

A correctly marked 3 in. brass cap stamped PAUL N. SCHERBAL RLS 6805 W.C. E. 30' 1988.

A correctly marked 3 in. brass cap stamped PAUL N. SCHERBAL RLS 6805 W.C. N. 30' 1988.

The cor. of secs. 13, 14, 23, and 24, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found monumented with a correctly marked 3 in. brass cap stamped PAUL N. SCHERBAL RLS 6805 1988.

The  $\frac{1}{4}$  sec. cor. of secs. 19 and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, has been destroyed by mining activity. The position was calculated based upon the recorded Map of Amended