

MINERAL SURVEY NO. 5061

FEET

Goldstrike and POST Lode Mining Claims, File No. 136730, of the Eureka County Official Records. The point for this corner is located within a haul road and was not remonumented at the time of this survey.

The $\frac{1}{4}$ sec. cor. of secs. 23 and 24, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found monumented with a correctly marked 3 in. brass cap stamped PAUL N. SCHERBAL RLS 6805 1988.

The South $\frac{1}{2}$ mile bet. secs. 19 and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found to be N. $0^{\circ}01'44''$ E, 2619.44 ft. dist., instead of N. $0^{\circ}04'$ E., 2618.88 ft., as approved.

The North $\frac{1}{2}$ mile bet. secs. 19 and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found to be N. $0^{\circ}03'36''$ E., 2616.87 ft. dist., instead of N. $0^{\circ}04'$ E., 2620.86 ft., as approved.

The line bet. secs. 24 and 25, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found to be S. $89^{\circ}17'45''$ W., 5321.46 ft. dist., instead of N. $89^{\circ}56'$ W., 5290.56 ft., as approved.

The South $\frac{1}{2}$ mile bet. secs. 23 and 24, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found to be N. $0^{\circ}01'25''$ E., 2628.48 ft. dist., instead of North, 2640.00 ft., as approved.

The North $\frac{1}{2}$ mile bet. secs. 23 and 24, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found to be N. $0^{\circ}01'21''$ E., 2628.48 ft. dist., instead of North, 2640.00 ft., as approved.

The line bet. secs. 13 and 24, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found to be S. $89^{\circ}31'06''$ W., 5323.24 ft. dist., instead as N. $89^{\circ}52'$ W., 5286.60 ft., as approved.

The $\frac{1}{4}$ sec. cor. of secs. 19 and 20, T. 36 N., R. 50 E., has been destroyed by mining activity. The position was calculated based upon the recorded Map of Amended Goldstrike and POST Lode Mining Claims, File No. 136730, of the Eureka County Official