FEET

Lode Mining Claims, file No. 136730, of the Eureka County Official Records.

The South ½ mile of the line bet. secs. 19 and 20, T. 36 N., R., 50 E., Mt. Diablo Meridian, was found to be N. 2°01'18" W., 2637.76 ft. dist., instead of N. 2°03' W., 2638.02 ft., as approved.

The South ½ mile of the line bet. secs. 19 and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found to be N. 0°01'44" E, 2619.44 ft. dist., instead of N.0°04' E., 2618.88 ft., as approved.

The North ½ mile of the line bet. secs. 19 and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found to be N. 0°03'36" E., 2616.87 ft. dist., instead of N. 0°04' E., 2620.86 ft., as approved.

The West ½ mile of the line bet. secs. 18 and 19, T. 36 N., R. 50 E., Mt. Diablo Meridian, was found to be N. 88°44'38" E., 2603.69 ft. dist., instead of N. 88°49' E., 2603.04 ft., as approved.

The cor. of Secs. 13, 18, 19, and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found monumented with an iron post, 2 1/2 ins. diam., firmly set showing 10 ins. above ground, with a properly marked brass cap.

The cor. of secs. 19, 24, 25, and 30, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, has been destroyed by mining activity. The position was calculated based upon the information recorded on Record of Survey File No. 10190 of the official Records of Eureka County, Nevada, and was not remonumented at the time of this survey due to current mining activity.

The \(\frac{1}{4} \) sec. cor. of secs. 19 and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, has been destroyed by mining activity. The position was calculated based upon the recorded Map of Amended Golstrike and POST Lode Mining Claims, File No. 136730, of the Eureka County Official Records. The point for this corner is located within a haul road and was not remonumented at the time of this survey.