

## MINERAL SURVEY NO. 5065

FEET

The cor. of secs. 1, 6, 7, and 12, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found monumented with an iron post, 2½ ins. diam., firmly set, showing 6 ins. above ground with a properly marked brass cap.

The cor. of secs. 13, 14, 23, and 24, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found monumented with a correctly marked 3 in. brass cap stamped PAUL N. SCHERBEL RLS 6805 1988.

The ¼ sec. cor. of secs. 13 and 24, T. 36 N., R. 49 E., Mt. Diablo Meridian, was not found. Point reestablished at proportionate distance. Not remonumented.

The cor. of secs. 11, 12, 13, and 14, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found monumented with a correctly marked 3 in. brass cap stamped CHILTON ENGINEERING 1970.

The monument for the ¼ sec. cor. of secs. 19 and 24, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, has been destroyed by mining activity. The position was calculated based upon the recorded Map of Amended Goldstrike and POST Lode Mining Claims, File No. 136730, of the Eureka County Official Records.

The ¼ sec. cor. of secs. 18 and 19, T. 36 N., R. 50 E., Mt. Diablo Meridian, was found monumented with a 2½ in. diam. BLM aluminum post, showing 10 ins. above ground, with an aluminum cap properly marked.

The ¼ sec. cor. of secs. 13 and 18, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found monumented with a correctly marked 3 in. brass cap showing 8 ins. above ground, stamped PAUL N. SCHERBEL RLS 6805 1984.

The ¼ sec. cor. of secs. 13 and 14, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found monumented with a correctly marked 3 in. aluminum cap stamped PLS 3535 1990.

The ¼ sec. cor. of secs. 12 and 13, T. 36 N., R. 49 E., Mt. Diablo Meridian, was found monumented with a correctly marked 3 in. aluminum cap stamped PLS 3535 1990.

The ¼ sec. cor. of secs. 7 and 12, Tps. 36 N., Rs. 49 and 50 E., Mt. Diablo Meridian, was found monumented