

Mineral Survey No. 5070

FEET	
	<p>Drill Hole No. SC 486 bears S. 87°41' E., 211.6 ft. dist., from Cor. No. 1 of the SAV No. 6A lode, 5.25 ins. diam., 540 ft. deep. No value.</p> <p>Drill Hole No. SC 287 bears N. 60°02' W., 284.5 ft. dist., from Cor. No. 1 of the SAV No. 7 lode, 5.25 ins. diam., 600 ft. deep. No value.</p> <p>Drill Hole No. SC 303 bears N. 77°10' W., 658.7 ft. dist., from Cor. No. 1 of the SAV No. 7 lode, 5.25 ins. diam., 700 ft. deep. No value.</p>
	<p>OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA</p>
	<p>The W $\frac{1}{16}$ sec. cor. of secs. 10 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 2 ft. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.</p> <p>The SW $\frac{1}{16}$ sec. cor. of sec. 10, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 6 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.</p> <p>The C-S $\frac{1}{16}$ sec. cor. of sec. 10, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 6 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap mkd. S $\frac{1}{16}$ S10 instead of C-S $\frac{1}{16}$ S10. R.L.S. 4643 stamped on cap.</p> <p>The $\frac{1}{4}$ sec. cor. of secs. 10 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 8 ins. above the ground, with a 1986 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.</p> <p>The C-N $\frac{1}{16}$ sec. cor. of sec. 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 8 ins. above the ground, with a 1986 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.</p> <p>The NE $\frac{1}{16}$ sec. cor. of sec. 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 10 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.</p> <p>The N $\frac{1}{16}$ sec. cor. of secs. 14 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., 6 ins. above the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.</p> <p>The E $\frac{1}{16}$ sec. cor. of secs. 10 and 15, T. 40 N., R. 53 E., MDM, was found monumented with an aluminum post, 2 ins. diam., flush with the ground, with a 1987 U.S. Dept. of Agriculture, Forest Service aluminum cap properly mkd. R.L.S. 4643 stamped on cap.</p>