

## Mineral Survey No. 5076

FEET

These improvements afford the most practical and economical means of developing each of the lodes.

Five hundred dollars or over has been expended in these improvements in such a manner as tends to the development of each lode of this survey, subsequent to its location and to the time since which common ownership and contiguity have prevailed; therefore, an undivided one-sixteenth interest in their value is hereby credited to each of the lodes.

No portion of or interest in these improvements has been credited theretofore as patent expenditures to any lode claims.

OTHER CORNER DESCRIPTIONS AND  
SUPPLEMENTAL DATA

Portions of Tps. 13 N., Rs. 45 and 46 E. are in the process of being surveyed under Group No. 723. At this time, the townships have not been approved.

The closing cor. of secs. 18 and 19, T. 13 N., R. 46 E., MDM, was found monumented with a stainless steel post, 2½ ins. diam., 6 ins. above the ground, with a U.S. Dept. of Interior, Cadastral Survey, B.L.M. brass cap properly mkd. and dated 1992. The cor. was found on top of an old leach pad.

The cor. of secs. 13 and 24, T. 13 N., R. 45 E., MDM, was found monumented with a stainless steel post, 2½ ins. diam., 4 ins. above the ground, with a U.S. Dept. of Interior, Cadastral Survey, B.L.M. brass cap properly mkd. and dated 1992.

U.S.L.M. 4974 was found on a 6 ft. diam. rock and earth platform, 2 ft. high, monumented with an iron post, 2 ins. diam., with a brass cap mkd. + USLM 4974. Found an old weathered 4 in. by 4 in. post, 4½ ft. in length, scribed with USMM laying on top of platform.

M.S. No. 4974 Chipmunk NO. 6 lode. Cor. Nos. 2 and 3 were found monumented with iron posts and brass caps, firmly set and properly mkd. Line 2-3 was found to be S. 16°03'16" W., 600.00 ft. dist., instead of S. 16°03'44" W., 600.00 ft. dist., as approved.

M.S. No. 4974 NEIL NO 5 lode. Cor. No. 3 is identical with Cor. No. 3, M.S. No. 4974 Chipmunk NO. 6 lode, described above. Cor. No. 2 was destroyed by mining activity and re-established at proportionate dist. on line bet. Cor. No. 3 and Cor. No. 3, M.S. No. 4974 NEIL NO 2 lode. Line 2-3 was found to be N. 16°03'16" E., 599.98 ft. dist., instead of N. 16°03'44" E., 600.00 ft. dist., as approved.

M.S. No. 4974 NEIL NO 2 lode. Cor. Nos. 3 and 4 were found monumented with iron posts and brass caps, firmly set and properly mkd. Cor. No. 2, identical with Cor. No. 2, M.S. No. 4974 NEIL NO 5 lode, was destroyed and re-established as described above. Line 2-3 was found to be S. 16°03'16" W., 599.98 ft. dist., instead of S. 16°03'44" W., 600.00 ft. dist., as approved. Line 3-4 was found to be N. 66°43'03" W., 1500.21 ft. dist., instead of N. 66°42'55" W., 1500.00 ft. dist., as approved.