

Mineral Survey No. 5103, Nevada

FEET

No portion of or interest in these improvements has been credited theretofore as patent expenditures to any lode claims.

OTHER CORNER DESCRIPTIONS
AND SUPPLEMENTAL DATA

The cor. of secs. 8, 9, 16, and 17, T. 38 N., R. 42 E., MDM, was found monumented with an iron post, $2\frac{1}{2}$ ins. diam., 15 ins. above the ground, surrounded by a mound of stone, with a U.S. Dept. of the Interior, Bureau of Land Management brass cap properly mkd. and firmly set.

The $\frac{1}{4}$ sec. cor. of secs. 9 and 16, T. 38 N., R. 42 E., MDM, was found monumented with an iron post, $2\frac{1}{2}$ ins. diam., 9 ins. above the ground, with a U.S. Dept. of the Interior, Bureau of Land Management brass cap properly mkd. and firmly set.

The E $\frac{1}{16}$ sec. cor. of secs. 9 and 16, T. 38 N., R. 42 E., MDM, was found monumented with an iron post, 1 in. diam., 12 ins. above the ground, surrounded by a mound of stone, with a U.S. G.L.O. brass cap, properly mkd. and firmly set.

The cor. of secs. 9, 10, 15, and 16, T. 38 N., R. 42 E., MDM, was found monumented with an iron post, $2\frac{1}{2}$ ins. diam., 8 ins. above the ground, with a U.S. Dept. of the Interior, Bureau of Land Management brass cap properly mkd. and firmly set.

The N $\frac{1}{16}$ sec. cor. of secs. 15 and 16, T. 38 N., R. 42 E., MDM, was found monumented with an iron post, 1 in. diam., 10 ins. above the ground, with a U.S. G.L.O. brass cap, properly mkd. and firmly set.

The C-E $\frac{1}{16}$ sec. cor. of sec. 16, T. 38 N., R. 42 E., MDM, was found monumented with a firmly set rebar, $\frac{5}{8}$ in. diam., 1 in. above the ground, with an aluminum cap, 2 ins. diam., mkd. Robert N. Caldwell R.L.S. 4233.

The C $\frac{1}{4}$ sec. cor. of sec. 16, T. 38 N., R. 42 E., MDM, was found monumented with a firmly set rebar, $\frac{5}{8}$ in. diam., 2 ins. above the ground with an aluminum cap, 2 ins. diam., mkd. Robert N. Caldwell, R.L.S. 4233.

The C-N $\frac{1}{16}$ sec. cor. of sec. 16, T. 38 N., R. 42 E., MDM, was found monumented with a firmly set rebar, $\frac{5}{8}$ in. diam., 2 ins. above the ground with an aluminum cap, 2 ins. diam., mkd. Robert N. Caldwell, R.L.S. 4233.

The N $\frac{1}{16}$ sec. cor. of secs. 16 and 17, T. 38 N., R. 42 E., MDM, was found monumented with an iron post, 1 in. diam., 2 ft. above the ground, surrounded by a mound of stone, with a U.S. G.L.O. brass cap, properly mkd. and firmly set.

The NE $\frac{1}{16}$ sec. cor. of sec. 16, T. 38 N., R. 52 E., MDM, was not set. The point for the NE $\frac{1}{16}$ sec. cor. of sec. 16 was established at the intersection of a line from the E $\frac{1}{16}$ sec. cor. of secs. 9 and 16 to the C-E $\frac{1}{16}$ sec. cor. of sec. 16, and a line from the N $\frac{1}{16}$ sec. cor. of secs. 15 and 16 to the C-N $\frac{1}{16}$ sec. cor. of sec. 16, not monumented.