

West Boundary of frac. T. 25 N. R. 23 E.

Chains

- 6.45 Head of drain, course W.
- 12.50 Top of low ridge, brs. NW. and SE.
- 16.30 Drain, course S. 55° W.
- 18.10 Draw, course West.
- 22.10 Low ridge, brs. E. and W.
- 29.80 Draw, course S. 60° W.
- 38.80 Draw, course S. 70° W.
- 40.00 Set an iron post for $\frac{1}{4}$ sec. cor. bet. secs. 7 and 12, with
brass cap stamped

$\frac{1}{4}$ S 12 in W. half
 S 7 in E. half
 1912 in S.

Build a mound of stone 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.

- 41.10 Draw, drains S. 65° W.
- 46.30 Draw, drains S. 75° W.
- 49.40 Dry drain, course S. 65° W.
Begin ascent of S. slope.
- 72.00 Top of ascent. Ridge, brs. N. 80° E. and S. 80° W.
Begin descent over NW. slope.
- 80.00 Set an iron post for the cor. of secs. 1, 6, 7 and 12,
with brass cap stamped

T 25 N S 6 in NE. quadrant
 R 23 E S 7 in SE. quadrant
 S 12 in SW. quadrant
 R 22 E S 1 in NW. quadrant
 1912 in S.
 5 notches on S. and 1 notch on N. edge

Build a mound of stone 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.

Land, rough and mountainous, barren.
Soil, rocky, 3rd rate.
No timber.

North bet. secs. 1 and 6.

Over very rough, mountainous land, descending over NW.
slope.

- 3.30 Draw, drains N. 45° W.
- 6.00 Bottom of descent. Dry drain, course W.
Begin ascent over steep south slope.