

## West bdy. of frac. T. 27 N. R. 21 E.

## Chains

Land, broken, rolling and grazing.  
Soil, stony and sandy, 3rd rate.

---

From the cor. of secs. 7, 12, 13 and 18, I run  
North on a true line bet. secs. 7 and 12.  
Continuing ascent along gentle SW. slope.

40.00 Set an iron post for  $\frac{1}{4}$  sec. cor. bet. secs. 7 and 12,  
with brass cap stamped

$\frac{1}{4}$  S 12 in W. half  
S 7 in E. half

Build a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

42.50 Top of ascent on SW. slope, thence along W. slope of ridge.

65.00 Begin gradual ascent to ridge.

80.00 Set an iron post for the cor. of secs. 1, 6, 7 and 12,  
with brass cap stamped

T 27 N S 6 in NE. quadrant  
R 21 E S 7 in SE. quadrant  
S 12 in SW. quadrant  
R 20 E S 1 in NW. quadrant  
5 notches on S. and 1 notch on N. edge

Build a mound of stone 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

Land, mountainous, - grazing.  
Soil, stony, 3rd rate.

---

From the cor. of secs. 1, 6, 7 and 12, I run  
North on a true line bet. secs. 1 and 6.  
Continuing ascent of SW. slope.

12.00 Top of ascent on W. slope .

Thence gradual descent of broken NW. slope.

40.00 Set an iron post for  $\frac{1}{4}$  sec. cor. bet. secs. 1 and 6, with  
brass cap stamped

$\frac{1}{4}$  S 1 in W. half  
S 6 in E. half

Build a mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of  
cor.

60.00 Top of low spur, bds. E. and W.

80.00 Set an iron post for the cor. of Tps. 27 and 28 N., Rgs.  
20 and 21 E., with brass cap stamped