

West bdy. of ^{frac.} T. 28 N. R. 21 E.

Chains

Land, rolling, broken, - grazing.
Soil, sandy, stony, 3rd rate.

From the cor. of secs. 7, 12, 13 and 18, I run

North bet. secs. 7 and 12.

Over gently rolling broken land.

19.75 Small draw, drains NW.

33.00 Draw, drains N. 25° W.

36.50 Draw, drains N. 85° W.

40.00 Set an iron post for the $\frac{1}{4}$ sec. cor. bet. secs. 7 and 12,
with brass cap stamped

$\frac{1}{4}$ S 12 in W. half
S 7 in E. half

Dig pits 18x18x12 ins. N. and S. of cor. 3 ft. dist.,
and raise a mound of earth 3 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high,
W. of cor.

58.50 Top of low spur, brs. E. and W.

77.00 Road, brs. N. 45° E. and S. 45° W.

80.00 Set an iron post for the cor. of secs. 1, 6, 7 and 12,
with brass cap stamped

T 23 N S 6 in NE. quadrant
R 21 E S 7 in SE. quadrant
S 12 in SW. quadrant
R 20 E S 1 in NW. quadrant
5 notches on S. and 1 notch on N. edge

Dig pits 18x18x12 ins. in each sec. 5 $\frac{1}{2}$ ft. dist., and
raise a mound of earth 4 ft. base, 2 ft. high, W. of cor.

Land, rolling, broken, - grazing.
Soil, stony, 3rd rate.

From the cor. of secs. 1, 6, 7 and 12, I run

North bet. secs. 1 and 6.

Over gently rolling land.

40.00 Set an iron post for $\frac{1}{4}$ sec. cor. bet. secs. 1 and 6, with
brass cap stamped

$\frac{1}{4}$ S 1 in W. half
S 6 in E. half

Dig pits 18x18x12 ins. N. and S. of cor. 3 ft. dist.